


Driver's Side Window Finish



Fabric of top is almost two inches too short. This causes water Intrusion. Top should cover the frame and overlap window/seal.