



HOME (INDEX PIP) SERVICES (SERVICES PHP) HOME (INDEX PHP)

REPAIR STATUS (STATUS.PHP)

REVIEWS (REVIEWS.PHP)



Please print this receipt for your records.

Note: Watch is not keeping time. Complete servicing required for automatic watch. Oils dry, weak amplitude. Rebuild self winding mechanism. Replace movement parts as necessary. Replace gaskets and test water resistance. Polishing is optional but recommended for best appearance. Polishing is performed as best as possible depending on watch finish and condition. Approximate repair time is 4-8 weeks from approval.

-	ervice				
*		PI	50	-	0
v	c		νŧ	٠.	c

Description

Price \$999.99

Overhaul

Full service overhaul - take apart the movement, clean old oil out and re-oil, replace parts as necessary, reassemble and time test for

72 hours

Movement disassembly required in order to access affected

components.

The following repair(s) will be completed during the overhaul process:

- Repair and rebuild self-winding mechanism
- Replace movement parts as necessary
- · Check parallelism between hands and dial
- Calibrate and timing check
- Cleaning & oiling of the movement

Seals / Gaskets

Replace gaskets and test water resistance.

\$99,99

Tune Up

Professional detailing / polishing service (as best as possible).

\$49.99

(\$149.99 value, discounted with service)

Subtotal: \$1,149.97

Total: \$1,247.70

Shipping: \$97.73

Note: Shipping rates calculated based on UPS signature required service with \$6,500 declared value insurance.



VISA



DISCOVER





Copyright © 2020 Watch Repairs USA | Privacy Policy (privacy_policy.php) | Terms & Conditions (terms_and_conditions.php) | Warranty Information (warranty.php) | Packing Tips (how_to_pack.php) | Wholesale / Trade Accounts (wholesale.php)

All trademarks and copyrights on this page are property of their respective owners. Watch Repairs USA is a separate entity not affiliated with the mark owner.

Display of any mark does not suggest endorsement or sponsorship by mark owner.



Brand: Cartier