

SERVICE ADVISOR:	TAG #	RO #
ANDRES GOMES		558421



WARRANTY	CUST. PAY	+\$1,500 ESP APPROVAL	RENTAL
Bumper to Bumper	ESP Other		

LINE	REPAIRS REQUESTED BY CUSTOMER	# LABOR HOURS	LABOR COST \$	PARTS COST \$	SUB-TOTAL \$
	Remove and		\$ 2,015.00	\$ 755.20	\$
	Replace Converter		\$	\$	\$
			\$	\$	\$
			\$	\$	\$
			\$	\$	\$
			\$	\$	\$
			\$	\$	\$
			\$	\$	\$
			\$	\$	\$
			\$	\$	\$

LINE	ADDITIONAL NEEDED SERVICES FOUND	# LABOR HOURS	LABOR COST \$	PARTS COST \$	SUB-TOTAL \$
			\$	\$	\$
			\$	\$	\$
			\$	\$	\$

COMMENTS:

	ESTIMATE \$
shop fees	FEE (12%) \$ 50.00
	TAXES % \$ 193.31
GRAND TOTAL ESTIMATE (ORIGINAL REQUESTED REPAIRS PLUS ADDITIONAL NEEDED REPAIRS)	\$ 3014.11

WORK APPROVED BY CUSTOMER	DOB:	DEPOSIT: \$
CUSTOMER NAME	SIGNATURE	DATE: