Here is a photo of the box from the new motor part # 326628-762 installed by Gillece Plumbing, Heating, Cooling & Electrical Inc.

The highest price I could find for the motor was $381.60
The highest price I could find for installation AFTER HOURS was $529.00
Total installation price should have been $910.60

Price paid $1500 - $200 (partial refund) = $1305 - $910.60 = $394.40 refund still owe to me.

Also no warranty was provided everyone's work carries a 30 day warranty.

I found all of these prices for the exact motor on the internet



BUDGET HVAC PARTS

high quality parts
at the lowest cost

Home About Shipping Privacy Returns Cancellations Contact
My Account | My Wishlist | My Cart (1 item) | Checkout | Log In

Fan Motors | Blower Motors | Capacitors | Contactors, Relays, Transformers | Condenser Fan Blade | Draft Inducer
Circuit Board, Control Board | Inducer Fan, Inducer Wheel | UV Bulbs | Ignitors, Sensors | Air Filters | Pressure Switch, Limit Switch

1 item / $296.00 / Checkout

SEARCH Search entire store here... go

Welcome to Budget HVAC Parts | Login or create an account.

Shopping Cart

Carrier Draft Inducer Assembly 326628-762 was added to your shopping cart.

	PRODUCT NAME	UNIT PRICE	QTY	SUBTOTAL	REMOVE
	Carrier Draft Inducer Assembly 326628-762	$296.00	1	$296.00	

Continue Shopping

UPDATE QTY

---

home | About Us | Privacy Policy | Send Email

THC

37667 CHERRY HILL ROAD WESTLAND, MICHIGAN 48186

TECHNICAL HOT AND COLD

BUILDING SERVICES • CERTIFIED WOMAN OWNED

Carrier Search

If you can't find it call us. We St

- AAON
- ADP
- Allen Bradley
- Allied
- Apparel
- Bard Manufacturing Company
- BKW
- Carrier Industrial
- Carrier
- Clearance Items
- Consolidate Industries
- Goodman
- Hoshizaki

Home > Carrier > Inducer Motor and Assembly > Carrier 326628-762 Inducer Motor

SPECIAL OFFER PayPal Get 6 months to pay on purchases of $99+
Check out with PayPal and choose Bill Me Later®
Subject to credit approval. See terms. US customers only.

Carrier 326628-762 Inducer Blower Motor



Carrier 326628-762 Inducer Motor

Item# 326628-762

$297.58

Availability: Usually ships the same business day

MIDWEST HVACPARTS
HEATING • AIR CONDITIONING • REFRIGERATION
866-982-HVAC (4822)

DO YOU KNOW WHAT YOU'RE LOOKING FOR?
SEARCH BY MANUFACTURER, PART NUMBER, SKU, MODEL NUMBER, or PART NAME.
SEARCH

Register | Log in
Shopping Cart (1)

24-Hour Online Ordering
Customer Service M-F: 866-982-4822

MIDWESTHVACPARTS.COM

HOME PAGE | NEW PRODUCTS | SHIPPING INFO | PRIVACY NOTICE | CONTACT US

CATEGORIES
MANUFACTURERS
INFORMATION

- Blog
- Shipping & Returns
- Privacy Notice
- New products

SHOPPING CART

Remove	Product(s)	Qty.	Total
☐	*Inducer Motor Kit - Bryant, Carrier 326628-762*	1	$315.00

Sub-Total: $315.00
Tax: Calculated during checkout
Shipping: Calculated during checkout
Total: Calculated during checkout

PART-$-MART
A "Parts Mart" for the "Part Smart"
OCFB Enterprises LLC

Search: GO Advanced search

Home » HVAC OEM » Carrier Corporation » Carrier Products 326628-762 INDUCER ASSEMBLY

Categories
HVAC
HVAC OEM
Tools
Special
Manufacturers
Help
Product Map (A-Z)
Sitemap
Contact us
Payment Methods
Terms of Use
Contact US Information
Undeliverable Items
Disclaimer/Terms of Sale
Hours of Operation/Holiday Hours
Return Policy

Carrier Products 326628-762 INDUCER ASSEMBLY

No image available

Carrier Products 326628-762 INDUCER ASSEMBLY

Details

SKU	326628-762
Weight	2.00 lbs
Our price:	**$381.60**

Options

Quantity 1

Add to cart | Add to wish list

Ask a question about this product

1-888-757-4774

My Account | Order Status | Customer Service

PexSupply.com

Free Shipping on Orders Over $300

Enter

PEX | HEATING | PLUMBING | FITTINGS | VALVES | HVAC | THER

Home > HVAC & Air Quality > Replacement Parts > Carrier Parts > Motors > Draft Inducer Motors

IMAGE UNAVAILABLE

Inducer Motor Assembly Kit

SKU: 326628-762 **Brand:** Carrier

Read **1** Review | Write a Review

QTY	PRICE
	$323.34 / each

ADD TO CART

In Stock! | Ships in 24-48 Hours
(2 Available)

Overview | Product Reviews | Q & A | Manuals

Description for Carrier 326628-762

PilotAIR Parts
HEATING ❊ COOLING ❊ APPLIANCES
1-336-514-9098

We have the resources to help locate your part
Phone assistance will be unavailable Thursday 11/28 & Friday 11/29 as we spend time with our families

Live Help offline click to email
FREE chat by Volusion

Shopping Cart
View Cart
Checkout
# of Item(s): 0
Total: $0.00

Limited Time
22
$290
Call for Details

Home | Resources | About Us | Service | Policies | Google+

Search

Tweet | Share | 0

Bookmark this page

Categories

- HVAC EQUIPMENT
- TRANE PARTS
- CARRIER PARTS
- GOODMAN PARTS
- ICP Parts
- LENNOX PARTS
- RHEEM PARTS
- MOTORS

Carrier®
FACTORY AUTHORIZED PARTS

326628-762 CARRIER INDUCER MOTOR KIT

Price: **$366.25**
Retail: $635.45
You Save: $269.20

Quantity: 1 Add To Cart



I did some research for **installation prices** on the internet.

FURNACE & HVAC REPAIR PRICE LIST

Igniter 199-299

Pilot igniter assembly $300-350

Capacitor replacement (outdoor heat pump) $199-$350

Capacitor replacement (indoor blower) $300-$450

indoor blower motor replacement

Heat pump/hvac Fan motor replacement $350-$550

Estimates: "Service Charge" rates (abbreviated S.C.) also known as "Trip Charge" or alternatively a "Diagnostic fee" are as follows:

Most established Appliance repair companies charge between $59 to $75 “Service fee”, "Service Charge", "Travel fee", or Initial/basic "Diagnostic fee” to show up.

Urgent", "Emergency Service" and "night/weekend" service charge for showing up to provide an initial assessment can cost between $75-$149. We suggest that you ask before the tech is dispatched.

SECTION 35

EMERALD HVAC

INDUCER FAN MOTOR

STOP

> ALL WORK THAT IS COMPLETED BY EMERALD HVAC WILL CARRY A 30 DAY LABOR WARRANTY AND A ONE YEAR PART WARRANTY
>DON'T FORGET THAT G.E.M. PLAN HOLDERS RECEIVE A 15% DISCOUNT

CODE #	DESCRIPTION	AFTER HOURS	REGULAR	G.E.M. HOLDERS
399040	Clean/remove obstructions	$ 89	$ 69	$ 59
400050	Adjust alignment & lubricate	$ 107	$ 83	$ 70
401100	Inducer motor assembly - Universal	$ 386	$ 338	$ 287
402100	Inducer motor assembly - OEM	$ 529	$ 481	$ 409
403075	Inducer motor only - Universal	$ 334	$ 298	$ 253
404075	Inducer motor only - OEM	$ 415	$ 379	$ 322
405066	Inducer wheel	$ 193	$ 161	$ 137
406050	Inducer draft board	$ 211	$ 187	$ 159
407100	Warranty inducer assembly	$ 208	$ 160	$ 136

I have had my routine seasonal servicing the last few years performed by Gillece Plumbing, Heating, Cooling & Electrical Inc. 412-279-8283. I called them and asked them to look at my furnace the fan was making a noise. I called at 8:00 AM they had a technician at my home by 10:30 am. After investigating the problem they told me that I needed an Inducer Motor Assembly Kit. At 12:45 pm they ordered the part and by 7:30 PM the work was done.

After doing all of the research on the price of the Inducer Motor Assembly Kit the highest price motor that I could find was $381.60 part # part # 326628-762.

After researching emergency price (I did not ask for emergency installation) the highest price that I could find was $529.00 I was never told about same day service being an extra charge.

This should bring the total installed price to $910.60. I was initially charged $1500. After being questioned by my daughter via phone about the high price, the company refunded me $195. So I paid $1305 for this work.

I believe that Gillece Plumbing, Heating, Cooling & Electrical Inc. should refund me an additional $394.40 which would bring the total installed price to $910.60. From all of the research that was performed this is a reasonable price to expect.

I called the original installer of my furnace was told they would have done the job which was Airendos and they said they would have put in a new motor and given a 1 year warranty for $745.62

I am 93 years old and believe that I was discriminated against because of my age and that I was overcharged on the price of the materials was well as the labor.