

Mercedes-Benz of North America

Date of Request

Owner Request For Assistance

24-Nov-17

Customer Last Name:

First

Request Made By:

TAMIMI

ASIM

CUST

Street Address:

City

State

Zip

2420 CHENEY

TUSTIN

CA

92782

Owner Telephone

HOME

Residence

Other

Yr

Model

Mileage

3109233919

11

E350

72,065

Vehicle World Code (VIN)

Delivery Date

Selling Dlr

Hat #

WDDHF5GB6BA323266

11/2/2010

5171

N/A

MIKE SCHMIDT

Owner Request:

GUEST REQUEST ASSISTANCE ON REPLACING DRIVERS SEAT BOTTOM COVER
SPLITTING AT MIDDLE SEAM - SEE PICS

Estimate:

Parts

Labor

\$375.00

\$480.00

Participation

11/24/17 9:45 AM

MB USA

25% OF PARTS 600.00

Dealer

Customer

Owner Request:

$375.00 - (93.75 \text{ 25\% parts}) = 281.25$
 $+ \text{Labor } 480.00$
 $= 761.25$

Participation

MB USA

Dealer

Customer

Estimate:

Parts

Labor

Owner Request:

Participation

MB USA

Dealer

Customer

Estimate:

Parts

Labor