



[Back to Dispatch: #119751718](#)

Non-Covered Cost Estimate



You have **1** estimated non-covered cost associated with your service request.

To proceed with your service request, **accept** the estimated non-covered costs. Then call Formula Air Hvac, Llc at (704) 251-9034 to complete the service.

Non-Covered Costs Details

Central Heating & A/C System

Replace	Evaporator Coil	\$1366.25
Reason Not Covered	Rust	

Contractor Note

The system lost 4 of the 6 pounds it holds and now cant cool properly.

Total estimated non-covered costs **\$1366.25**

*American Home Shield cannot guarantee the accuracy of this estimate, For exact costs, contact the contractor

