



WORLDWIDE EQUIPMENT -- COLUMBIA
707 CHEROKEE LANE
WEST COLUMBIA, SC 29169
PHONE : (803) 926-2900

*** Customer Review ***

Date / Time: 4/10/2023 12:22:46PM
Repair Order: 124242
Customer: 100553
Branch: 87
Invoice Total: \$4,089.60

Cash

Page 1 of 3

Bill To: Dior Express
14425 BALLANTYNE LAKE ROAD
CHARLOTTE, NC 28277

Ship To: Dior Express
14425 BALLANTYNE LAKE ROAD
CHARLOTTE, NC 28277

Customer P/O: PAMELAGLOVER

Completion Date:

Unit Number: 001 **Model Year: 2018** **Make/Model: KENWORTH T680**
Type: Class 8 **VIN: 1XKYD49X5JJ184673** **Meter: 479098 Miles**
In-Service Date: 05/26/2017 **ECM Reading: 18581**

Task: 1 **045-000000** **Engine System** **Department: Service**

Complaint: C/S THE CEL/SEL ARE ON AND DERATED. PLEASE CHECK AND ADVISE.

TOWED IN BY CAMPBELLS

ATTACHED PREVIOUS REPAIR HISTORY TO REFERENCE - JUST RELEASED FROM DEALER IN FLORIDA.

Correction: PULLED INTO THE SHOP AND CONNECTED THE SERVICE TOOL TO INSPECT FOR FAULT CODES. FAULTS APPEAR TO BE RELATED TO THE COOLING SYSTEM. REFERENCE TASK 2.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	DIAG	Diagnostic Sweep	Misc	1.00	100.00	100.00
Task 1 Subtotals				Parts:		\$0.00
				Labor:		\$94.50
				Miscellaneous:		\$100.00
				Task 1 Totals:		\$194.50

Task: 2 **042-00000** **Cooling System** **Department: Service**

Complaint: C/S THE LOW COOLANT LIGHT CAME ON TWICE, THEY ADDED COOLANT DUE TO LEVEL AND NOTICED THERE IS FLUID RESIDUE ON THE LEFT REAR SIDE OF THE ENGINE BEHIND THE MOUNTED FUEL FILTER. PLEASE CHECK AND ADVISE.

Correction: CONNECTED THE COOLING SYSTEM PRESSURE TESTING EQUIPMENT. PERFORMED A PRESSURE TEST ON THE COOLING SYSTEM AND FOUND THE OVERFILL SURGE TANK SIDE CAP HAS FAILED AND LEAKING. SYSTEM IS NOT HOLDING PRESSURE. WHILE RUNNING THE UNIT FOUND THE COMBUSTION GASES IN THE COOLANT. REQUIRED TO CHECK FOR A BAD COOLER, MAY BE A POSSIBLE BLOWN COOLER OR CRACKED CYLINDER HEAD. COOLANT IS CURRENTLY RUNNING INTO THE EXHAUST AND BOILING OFF. ALSO, FOUND THE FRONT STRUCTURE IS CURRENTLY LEAKING. REMOVED THE PIPE FROM THE EGR COOLER AND SCOPED, FOUND DRY AND GOOD. REQUIRED TO PULL THE TURBO AND EXHAUST MANIFOLD FOR CHECKS FOR LEAKS.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	N5348001	CAP-PRESSURE	Part	EA	1.00	63.95
Task 2 Subtotals				Parts:		\$63.95
				Labor:		\$1,701.00
				Task 2 Totals:		\$1,764.95

Task: 3 **013-000000** **Brake System - Diagnose** **Department: Service**



WORLDWIDE EQUIPMENT -- COLUMBIA
707 CHEROKEE LANE
WEST COLUMBIA, SC 29169
PHONE : (803) 926-2900

*** Customer Review ***

Date / Time: 4/10/2023 12:22:46PM
Repair Order: 124242
Customer: 100553
Branch: 87
Invoice Total: \$4,089.60

Cash

Page 2 of 3

Bill To: Dior Express
14425 BALLANTYNE LAKE ROAD
CHARLOTTE, NC 28277

Ship To: Dior Express
14425 BALLANTYNE LAKE ROAD
CHARLOTTE, NC 28277

Customer P/O: PAMELAGLOVER

Completion Date:

Complaint: C/S THE DRIVER SIDE BRAKES ARE CRACKED, INSPECT BRAKES AND ADVISE.

Correction: INSPECTED THE BRAKES AND FOUND THE STEER AXLE SHOES ARE CRACKED AND SEPARATING.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
				Task 3 Subtotals	Parts:	\$0.00
					Labor:	\$189.00
					Task 3 Totals:	\$189.00

Task: 4 **013-010004** **Brakes - Front Brakes/Drums - Replace**
Complaint: REPLACE STEER AXLE BRAKES

Department: Service

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	4719ES2-PR	RELINED GRIPPER-C65445-Core	Inherent	2.00	55.64	111.28
	GG4719ES2G	BRAKE SHOES REMAN KIT WITH	Part	1	103.19	206.38
		HARDWARE C65445				
	4719ES2-PR	RELINED GRIPPER-C65445-Core	Part	1	55.64	(111.28)
	55710B	BRAKE DRUM 16.50 X 5.0 BA	Part	EACH	409.27	818.54
				Task 4 Subtotals	Parts:	\$1,024.92
					Core Charge:	\$111.28
					Core Ret:	(\$111.28)
					Labor:	\$567.00
					Task 4 Totals:	\$1,591.92



WORLDWIDE EQUIPMENT -- COLUMBIA
707 CHEROKEE LANE
WEST COLUMBIA, SC 29169
PHONE : (803) 926-2900

***** Customer Review *****

Date / Time: 4/10/2023 12:22:46PM
Repair Order: 124242
Customer: 100553
Branch: 87
Invoice Total: \$4,089.60

Cash

Page 3 of 3

Bill To: Dior Express
14425 BALLANTYNE LAKE ROAD
CHARLOTTE, NC 28277

Ship To: Dior Express
14425 BALLANTYNE LAKE ROAD
CHARLOTTE, NC 28277

Customer P/O: PAMELAGLOVER

Completion Date:

Payment Method

Cash

Totals

Total Parts:	\$1,088.87
Total Core Chg:	\$111.28
Total Core Ret:	(\$111.28)
Total EHC:	\$0.00
Total Labor:	\$2,551.50
Total Miscellaneous:	\$100.00
Total Shop Supplies:	\$255.15
Invoice Subtotal:	\$3,995.52
Total Tax:	\$94.08
Invoiced Total:	\$4,089.60

WE have just opened a new Full Service location @ 295 Access Road Spartanburg South Carolina, Phone # (864) 814-7100 !

****Hours of Operation: Monday-Friday 7:00AM-MIDNIGHT. Saturday 7:30AM-4:00PM****

We value your opinion and want to hear from you about the quality of our service , our Division Manager - Chris Davis can be reached at 803-331-9935.

DISCLAIMER OF WARRANTIES: Any warranties on the products sold herby are those made by the manufacturer. The seller, WORLDWIDE EQUIPMENT, herby expressly disclaims all warranties, either expressed or implied, including any implied warranty of the merchantability or fitness for a particular purpose, and WORLDWIDE EQUIPMENT neither assumes nor authorizes any person to assume for it any liability in connection with the sale of said products.

No material is to be returned without permission. Claims on returns must be made within ten days accompanied with this invoice. returns are subject to 25% handling charge. Exchange core deposits will not be refunded after 10 days. No returns on electrical parts. Any freight charges on emergency/special orders are customer's responsibility.

TERMS: Net 30 Days. A late charge of up to 1.5% PER MONTH may be added to all Past Due Balances. Should it be necessary to have a lawyer collect this account Applicant/Buyer agrees to pay the lawyer's fees and expenses, including court costs.

Pro Billing TERMS apply to all Pro Billing invoices.

!!!NOW OFFERING MOBILE SERVICE TRUCK REPAIRS. Please call to speak with our Service Manager for more information. (803) 926-2900