



Kenworth of Jacksonville

1121 Suemac Rd Jacksonville, Florida 32254

Phone: (904) 739-2296



Case Number: 12593849

Repair Order Number: 74479

Purchase Order Number: N/A

Service Advisor: blaise, shawn - Case Date 2023-03-09 08:45:04 -0500

Customer: Dior Express

Unit Number: 001



Address: FL

Phone: (415) 481-7070

Fax: N/A

Customer Number: 00100

Asset: 2018 Kenworth T680

Serial Number: JJ184673

VIN: 1XKYD49X5JJ184673

Engine: ISX15

Engine Hours: 18572

Mileage: 478774 Miles

Warranty Start: 2017-05-26 12:00:00 -0400

In Service: 5 Years 10 Months

Item	Operation Name	Labor Hours	Additional Charges	Totals
1	<p>Oil Engine--6235200</p> <p>Complaint: tag 1165 spot 11</p> <p>Burnt oil smell coming from engine, possible oil smell coming from top of front cover.</p> <p>Cause: Found front crank seal and front cover leaking oil. The oil is burning off on the hot engine block causing it to smell.</p> <p>Started on repairs, have radiator removed.</p> <p>replaced front gear housing, housing gasket, housing bolts, fuel pump idler bolts, camshaft idler bolts, timed gear train, replaced air comp and HP fuel pump gaskets, replaced oil and oil filter.</p> <p>Labor:</p> <p>Parts:</p> <p>-(1.0) [5575513CUM] CAM GEAR BOLT -(1.0) [5719778CUM] CAM COVER GSK -(1.0) [4299125CUM] CAM ORING -(1.0) [3685556CUM] GASKET/ORING -(44.0) [10W30] OIL -(1.0) [3685510CUM] GEAR GASKET HOUSING -(1.0) [5658175CUM] SEAL RECT -(1.0) [4299124CUM] ORING -(3.0) [3896408CUM] BOLT, GEAR -(6.0) [3681174CUM] GEAR BOLT -(1.0) [3685173CUM] OIL SEAL -(3.0) [3882922] BOLT GEAR -(1.0) [5440813CUM] COMP GASKET -(1.0) [3687007CUM] SEAL STRIP F COVER -(1.0) [3691011CUM] FRONT COVER -(1.0) [LF14000NN] OIL FILTER -(1.0) [5468170CUM] GEAR HOUSING -(2.0) [3163075] PAINT -(4.0) [4620PAL] BRAKE CLEAN -(13.0) [3680882CUM] BOLT -(1.0) [MISC] PARTS</p>	32		<p>\$5,600.00</p> <p>\$2,438.58</p>

Labor: \$5,600.00

Parts: \$2,438.58

Shop Supplies: \$300.00



Kenworth of Jacksonville

Customer: Dior Express

Unit Number: 001

Case Number: 17536001

Asset: 2018 Kenworth T680

VIN: 1XKYD49X5JJ184673



Taxes: \$625.39

Total: \$8,963.97

Notes:

[3/9/2023 at 08:46 am EST] - Unit 001 was checked in at Kenworth of Jacksonville , arrival time: . NOTE: dwell

Repair status set to Checked-in.

[3/9/2023 at 08:46 am EST] - Approval Requested for the estimate version 1. View the estimate. NOTE: dwell time

Repair status set to Hold (auth).

[3/9/2023 at 08:46 am EST] - Asset is Ready. NOTE: dwell time

Repair status set to Complete (here).

[3/16/2023 at 08:56 am EDT] - Approval Requested for the estimate version 2, total \$9,049.18. View the estimate. NOTE: Please let me know if we can proceed.

Thank you,

Renee

Repair status set to Hold (auth).

[3/16/2023 at 09:11 am EDT] - Approved

[3/16/2023 at 09:13 am EDT] - Approved

[3/20/2023 at 07:32 am EDT] - Customer sent cc auth form and pics via email to have ready. Save in my files if anyone need it to process payment. (FYI to all)

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW AND SIGN: I UNDERSTAND THAT UNDER STATE LAW I AM ENTITLED TO A WRITTEN ESTIMATE IF MY FINAL BILL WILL EXCEED \$100. ☐ I REQUEST A WRITTEN ESTIMATE. ☐ I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COST DO NOT EXCEED \$_____, THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT WRITTEN APPROVAL. ☐ I DONOT REQUEST A WRITTEN ESTIMATE. This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal. This estimate is subject to tear down and inspection and is valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish the necessary materials. I understand any costs verbally quoted are an estimate only and not binding. Your employees may operate vehicle for inspecting, testing and delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. AUTHORIZED SIGNED _____ DATE: ____/____/____
Payment by ; ☐ Cash, ☐ Charge, ☐ Credit Card, ☐ Check