

Work Order : 139262

either . 2 jobs in one.

6 CORRECTION: I put the curtain up and it is a little bit long but it fits and is long enough. May need some more velcro tabs. i ordered some. Then i had to rob some curtains out of the same lot unit to install in this unit to get the customers gone and ordered them to put back in the lot unit. stock # 1459348

7 COMPLAINT: THE WALL PAPER ON PANELING ON WALL ABOVE SHOWER IS PELLING

7 CAUSE: peeling paper or seam tape wall paper.

7 CORRECTION: I peeled the paper off the wall and exposed a badly cut panel done by the factory. So i used the paper i peeled off and covered a trim the nail into the corner and laid the seam tape or the bad cut on the wall and hid all of the area to fix the issue.

8 COMPLAINT: THE WALL PAPER BOARDER IN BATHROOM IS BUBBLING IN PLACES

8 CAUSE: Bubbes again.

8 CORRECTION: Pushed them out again.

9 COMPLAINT: THE KITCHEN WALL PAPER BOARDER IS BUBBLING IN A FEW SPOTS ALSO

9 CAUSE: Bubbled up again.

9 CORRECTION: Pushed them out again.

10 COMPLAINT: TRIM ON WALL BY THE BATHROOM DOOR IS LOOSE CUSTOMER HAS PUSHED BACK IN PLACE A COUPLE OF TIMES

10 CAUSE: Loose trim.

10 CORRECTION: Nail down and putty over the nail heads.

11 COMPLAINT: WOOD AROUND THE REAR TV CABINET TWO OF THE WOOD MOLDINGS HAVE COME LOOSE

11 CAUSE: Loose trims.

11 CORRECTION: Nail them back on tight. Then putty over the nail heads. Then fix damage to some of the corner cuts.

12 COMPLAINT: THE CABEL ON THE SPRING ON BED SLIDE OUT IS GETTING CAUGHT ON SLIDE WHEN GOING OUT THEN COMMING BACK IN

12 CAUSE: White plastic is popping on the edge of bed when it goes out on the black teflon guides.

12 CORRECTION: I cut a wedge on the end of the teflon rails and then i put screws into the face of the white plastic cover trims to fix the issue.

13 COMPLAINT: THE KITCHEN SINK THE ATTACHMENT THAT HOLDS IT TO THE COUNTER HAS CAME OFF IS SITTING ON THE COUNTER TOP BY SINK

13 CAUSE: Bot stud fell off and the wing nut and bracket.

13 CORRECTION: I had to reinstall the stud back into the sink base and make it tight so it won't come out again. Then i reinstalled the bracket i found and then the wing nut and tightened it on the sink bottom and put a back up nut on as well.

14 TOP OFF LP TANK