




LOOK THE SILICONE – NOT NEW GASKET SEALS – LOOK THE OIL – THEY USED SILICONE TO STOP THE OIL



LOOK THE OIL LEAK WHICH THEY FIXED



OIO

LOOK THE SILICONE, INSTEAD OF REPLACING THE GASKET SEALS



LOOK THE SILICONE, INSTEAD OF REPLACING THE GASKET SEALS