



Master Record Number	24C000101
Type Of Crash:	InjuryNonIncapacitating
Approved By	VINSON,M

Tennessee Electronic Traffic Crash Report

Incident Information

Date of Crash 07/07/2024	Day of Crash Sunday	Local Agency Number		Reporting Agency Name Bolivar Police Department	Agency Tracking Number TN0350100	
Time of Crash 10:00	Time Notified 10:05	Time Arrived 10:09	County Hardeman		City BOLIVAR	
Total Vehicles 2	Total Occupants 2	Total Non-Occupants 0	Total Killed 0	Total Injured 1	Total Un-Injured 1	
Hit and Run No	Solved? No	Police Pursuit N	School Bus Involved? No	Photos Taken? No	By	Photographer Name
Area On Roadway			Interchange Related?	Intersect Type Four-Way		
Block Number 0		Roadway Number	Roadway Name 1604 W MARKET ST			Suffix
Est Distance 0	Distance Type	Direction	From Highway Number/Intersection		Suffix	Intersect Number 0.00
Roadway Local ID				Intersect Local ID		
Relation to Junction Intersection-Related			Relation to Roadway On Roadway		Route Signing	
Work Zone			Construction Zone			
Construction Location			Workers Present			
First Hamful Event Motor Vehicle-In-Transport On Same Roadway			Trafficway Type Trafficway-OPEN			
Weather Conditions Clear		Light Conditions Daylight		Latitude 35.279911	Longitude -89.0246236	Rail Crossing ID
Manner of Collision Front to Rear						
1st Collision Factor		2nd Collision Factor		3rd Collision Factor		

Investigating Officer Details

Investigation Complete Yes	Rank Officer	First Name Chris	Middle Initial	Last Name Deming	Suffix
Badge Number 524	District/Zone	Car Number		Report Date 07/07/2024	

Vehicle Number 1	No. of Occupants 1	Driver Presence Driver Operated
----------------------------	------------------------------	---

Driver Information

First Name RHONDA	Middle Initial M	Last Name REED	Suffix	Date of Birth 07/16/1971	Age 52
Address Line 1 87 CARTHAGE R		Address Line 2		City JACKSON	State TN
Phone 1 7315186280	Phone 2	Phone 3	Race BLACK	Ethnicity NOT OF HISPANIC	Gender FEMALE
Air Bag Air Bag Available - No Deployment					
Safety Equipment Shoulder And Lap Belt Used					
Drivers License Number 095919146	Licence State TN	Expiration Date 5/22/2032 5:00	License Class D	License Status	Seat Position Front Seat Left Side
Endorsements 1 None	Complied With?	Endorsements 2	Complied With?	Endorsements 3	Complied With?
Restrictions 1 None	Complied With?	Restrictions 2	Complied With?	Restrictions 3	Complied With?
Ejected Not Ejected	Ejection Path			Trapped/Extricated Not Trapped	
Injury Code No Injury	Medical Transport	Ambulance/Hospital			

Driver Conditions and Actions

Hit and Run? No Hit And Run	Driver/Vehicle Maneuver	Distraction Unknown
Driver's 1st Condition Appeared Normal	Driver's 2nd Condition	Driver's 3rd Condition
Driver's 1st Action Unknown	Driver's 2nd Action	
Driver's 3rd Action	Driver's 4th Action	

Alcohol and Drugs

Presence of Alcohol	Determination Method	Alcohol Test Status Test Not Given		
1st Alcohol Test Type Not Tested	1st Alcohol Test Result Not Administered	2nd Alcohol Test Type	2nd Alcohol Test Result	
Presence of Drugs	Determination Method	Drug Test Status Test Not Given		
1st Drug Test Type Not Tested For Drugs	1st Drug Test Result	2nd Drug Test Type	2nd Drug Test Result	3rd Drug Test Result

Driver Violations

1st Violation	1st Violation Category	1st Violation Description	1st Violation Statute
2nd Violation	2nd Violation Category	2nd Violation Description	2nd Violation Statute
3rd Violation	3rd Violation Category	3rd Violation Description	3rd Violation Statute
4th Violation	4th Violation Category	4th Violation Description	4th Violation Statute
5th Violation	5th Violation Category	5th Violation Description	5th Violation Statute

Vehicle Information

Owner Same as Driver? Y	Owner First Name RHONDA	Owner Middle Name M	Owner Last Name REED	Owner Suffix
Street 1 87 CARTHAGE R		Street 2	City JACKSON	State TN
Phone Number 2	Phone Number 3	Vehicle Year 2019	Vehicle Make NISSAN	Vehicle Model ALTIMA
VIN 1N4BL4DV9KC187226	License Plate Number 856BLNF	State TN	Exp Year 2024	Body Code Four-Door, Sedan Hardtop
HAZMAT?	FMCSA Reportable? N	Bus Use Not Used As School Bus	Unit Type Motor Vehicle In-Transport	
Gross Weight			Vehicle Configuration	
Vehicle Operation Type Personally Owned/Used			Cargo Body Type	
1st Factor		2nd Factor		3rd Factor
Insurance 1 2023189074	Insurance 1 Type Vehicle	Insurance 1 Carrier Direct	Insurance 1 Start Date 5/20/2024 12:00:00 AM	Insurance 1 End Date 5/20/2025 12:00:00 AM
Insurance 2	Insurance 2 Type	Insurance 2 Carrier	Insurance 2 Start Date	Insurance 2 End Date
Insurance 3	Insurance 3 Type	Insurance 3 Carrier	Insurance 3 Start Date	Insurance 3 End Date

Vehicle Damage and Roadway Characteristics

Most Harmful Event Motor Vehicle-In-Transport On Same Roadway		Emergency Use? N	Over Underride No Underride Override	Fire in Vehicle? N
Events 1 Motor Vehicle-In-Transport On Same Roadway		Events 2		Events 3
Events 4		Events 5		Events 6
Point of First Impact FrontEnd		Extent of Damage Disabling Damage		Officer Damage Estimate GreaterThan400Dollars
Areas of Vehicle Damage FrontEnd				
Vehicle Special Use No Special Use	Towed? TowedDueToVehicleDamage	Towed Where? White's	1st Trailer	1st Trailer Licence Plate Information
2nd Trailer	2nd Trailer Licence Plate Information		3rd Trailer	3rd Trailer Licence Plate Information
Travel Direction West	Traveling On W Market			
Trafficway Flow Two-Way Not Divided		Roadway Surface Type Concrete	Number of Travel Lanes 2	
Trafficway Hazards None				
Traffic Control Devices TCS Without Ped Signal		Traffic Control Device Functioning Yes		Roadway Route Signing MunicipalRoute
Roadway Surface Conditions Dry		Roadway Character Alignment Straight		Roadway Character Profile Level
Speed Limit 45	Access Control No Control			

Commercial Carrier Information

US DOT	Carrier Name		Carrier Type		ICC MC	TN DOS
Address Line 1		Address Line 2		City	State	Zip Code Phone
1st Hazardous Materials	HAZMAT Class	Placard? N	Placard #	Released? N	Hazardous Materials Released	
2nd Hazardous Materials	HAZMAT Class	Placard? N	Placard #	Released? N	Hazardous Materials Released	
3rd Hazardous Materials	HAZMAT Class	Placard? N	Placard #	Released? N	Hazardous Materials Released	

Occupant

Person Type Driver						
First Name RHONDA	Middle Name M	Last Name REED		Suffix	Date Of Birth 7/16/1971 5:00:00 AM	Age 52
Address Line 1 87 CARTHAGE R		Address Line 2		City JACKSON	State TN	Zip Code 38305
Phone 1 7315186280	Phone 2		Phone 3	Gender FEMALE	Seating Position Front Seat Left Side	
Airbag Air Bag Available - No Deployment			Safety Equipment Shoulder And Lap Belt Used			
Ejected Not Ejected		Ejection Path			Trapped/Extricated Not Trapped	
Injury Code No Injury		Medical Transport			Ambulance/Hospital	

Vehicle Number 2	No. of Occupants 1	Driver Presence Driver Operated
----------------------------	------------------------------	---

Driver Information

First Name STEPHANIE		Middle Initial L	Last Name SHELLY		Suffix	Date of Birth 06/22/1972	Age 52
Address Line 1 1995 CATFISH L		Address Line 2		City CRUMP	State TN	Zip Code 38327	
Phone 1 9017363767	Phone 2	Phone 3	Race WHITE	Ethnicity NOT OF HISPANIC	Gender FEMALE	Air Bag Air Bag Available - Switched Off	
Safety Equipment Shoulder And Lap Belt Used							
Drivers License Number 096237529	Licence State TN	Expiration Date 2/11/2030 6:00	License Class D	License Status		Seat Position Front Seat Left Side	
Endorsements 1 None		Complied With?	Endorsements 2		Complied With?	Endorsements 3	
Restrictions 1 None		Complied With?	Restrictions 2		Complied With?	Restrictions 3	
Ejected Not Ejected		Ejection Path				Trapped/Extricated Not Trapped	
Injury Code Possible Injury		Medical Transport Yes		Ambulance/Hospital BOLIVAR ER			

Driver Conditions and Actions

Hit and Run? No Hit And Run	Driver/Vehicle Maneuver	Distraction None
Driver's 1st Condition Appeared Normal	Driver's 2nd Condition	Driver's 3rd Condition
Driver's 1st Action None	Driver's 2nd Action	
Driver's 3rd Action	Driver's 4th Action	

Alcohol and Drugs

Presence of Alcohol	Determination Method	Alcohol Test Status Test Not Given			
1st Alcohol Test Type Not Tested	1st Alcohol Test Result Not Administered	2nd Alcohol Test Type	2nd Alcohol Test Result		
Presence of Drugs	Determination Method	Drug Test Status Test Not Given			
1st Drug Test Type Not Tested For Drugs	1st Drug Test Result	2nd Drug Test Type	2nd Drug Test Result	3rd Drug Test Type	3rd Drug Test Result

Driver Violations

1st Violation	1st Violation Category	1st Violation Description	1st Violation Statute
2nd Violation	2nd Violation Category	2nd Violation Description	2nd Violation Statute
3rd Violation	3rd Violation Category	3rd Violation Description	3rd Violation Statute
4th Violation	4th Violation Category	4th Violation Description	4th Violation Statute
5th Violation	5th Violation Category	5th Violation Description	5th Violation Statute

Vehicle Information

Owner Same as Driver? Y	Owner First Name STEPHANIE	Owner Middle Name L	Owner Last Name SHELLY	Owner Suffix	
Street 1 1995 CATFISH L	Street 2	City CRUMP	State TN	Zip Code 38327	Phone Number 1 9017363767
Phone Number 2	Phone Number 3	Vehicle Year 2015	Vehicle Make NISSAN	Vehicle Model ALTIMA	Color BLACK
VIN 1N4AL3APXFC160537	License Plate Number 261BBFG	State TN	Exp Year 2025	Body Code Four-Door, Sedan Hardtop	
HAZMAT?	FMCSA Reportable?	Bus Use Not Used As School Bus	Unit Type Motor Vehicle In-Transport		
Gross Weight			Vehicle Configuration		
Vehicle Operation Type Personally Owned/Used			Cargo Body Type		
1st Factor		2nd Factor		3rd Factor	
Insurance 1 952068995	Insurance 1 Type Vehicle	Insurance 1 Carrier Progressive	Insurance 1 Start Date 3/3/2024 12:00:00 AM	Insurance 1 End Date 9/3/2024 12:00:00 AM	
Insurance 2	Insurance 2 Type	Insurance 2 Carrier	Insurance 2 Start Date	Insurance 2 End Date	
Insurance 3	Insurance 3 Type	Insurance 3 Carrier	Insurance 3 Start Date	Insurance 3 End Date	

Vehicle Damage and Roadway Characteristics

Most Harmful Event Motor Vehicle-In-Transport On Same Roadway		Emergency Use? Use?	Over Underride No Underride Override	Fire in Vehicle? Vehicle?
Events 1 Motor Vehicle-In-Transport On Same Roadway		Events 2		Events 3
Events 4		Events 5		Events 6
Point of First Impact RearEnd		Extent of Damage Functional Damage		Officer Damage Estimate GreaterThan400Dollars
Areas of Vehicle Damage RearEnd				
Vehicle Special Use No Special Use	Towed? DrivenFromScene	Towed Where?	1st Trailer	1st Trailer Licence Plate Information
2nd Trailer	2nd Trailer Licence Plate Information		3rd Trailer	3rd Trailer Licence Plate Information
Travel Direction West	Traveling On W Market			
Trafficway Flow Two-Way Not Divided		Roadway Surface Type Concrete	Number of Travel Lanes 2	
Trafficway Hazards None				
Traffic Control Devices TCS Without Ped Signal		Traffic Control Device Functioning Yes		Roadway Route Signing MunicipalRoute
Roadway Surface Conditions Dry		Roadway Character Alignment Straight		Roadway Character Profile Level
Speed Limit 45	Access Control No Control			

Commercial Carrier Information

US DOT	Carrier Name		Carrier Type		ICC MC	TN DOS
Address Line 1		Address Line 2		City	State	Zip Code Phone
1st Hazardous Materials	HAZMAT Class	Placard?	Placard #	Released?	Hazardous Materials Released	
2nd Hazardous Materials	HAZMAT Class	Placard?	Placard #	Released?	Hazardous Materials Released	
3rd Hazardous Materials	HAZMAT Class	Placard?	Placard #	Released?	Hazardous Materials Released	

Occupant

Person Type Driver						
First Name STEPHANIE		Middle Name L	Last Name SHELLY		Suffix	Date Of Birth 6/22/1972 5:00:00 AM
Address Line 1 1995 CATFISH L		Address Line 2		City CRUMP	State TN	Zip Code 38327
Phone 1 9017363767		Phone 2		Phone 3	Gender FEMALE	Seating Position Front Seat Left Side
Airbag Air Bag Available - Switched Off			Safety Equipment Shoulder And Lap Belt Used			
Ejected Not Ejected		Ejection Path			Trapped/Extricated Not Trapped	
Injury Code Possible Injury		Medical Transport Transported			Ambulance/Hospital BOLIVAR ER	

Narrative

On Sunday, 07/07/2024, I responded to a two vehicle mva with injuries at 1604 W Market, the intersection of W Market and Old Highway 64.

On scene, I observed two vehicles occupying the inside travel lane of W Market st. Stephanie Shelly, driver of vehicle two, advised that she was stopped at the red light at that intersection when vehicle one struck her from behind.

Vehicle one was parked behind vehicle two with substantial front end damage on vehicle one. Vehicle two was just ahead of the white stop line for the intersection with substantial damage to the rear end.

Report Media

Case Photos



i [unreadable]

GENERAL

ESD